



Burbank Jet.







...








- 0420 Lawrence Engineering Spot 03
- 0420 Jergens, Andrew Company Spots 12-13-14-17
- 0421 S. P. Storage Track
- 0422 Continental Hagen Corp. Code 99
- 0423 Lead Track Code 91
- 0425 Bormann Steel Company Code 99
- 0458 Light Sales Co. Spot 26












3 6 6			,
TO ZONE 2		ZONE C	2
	TRA CK	INDUSTRY SERVED	CAP
SAN FERNANDO RO.	0227	Sanitek Products Inc. Spot 02	115 1
TIR	0230	General Portland Cement Co. Spot 02	90 1
MAIN LINE LINE SUDER	0232	Vacant Spot Oli	<b>6</b> 0
	0232	Warrington Bros. Mfg. Co. Spot 05	60 1
FERNANDO BD 0220 0222	0233	Vacant Code 91- Spot 05	9 <sup>C</sup>
2 C 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	0234	Harrington Tool Co. Spot 02	1.
TO RADE	0238	Lead Track Code 91	<b>179</b> 5
Do vois	0238		1 Com 262
BLV D		Spots #33#-34-35-36-37-38	4
10/	0238	Active Window Co. Spot 35	60 1
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	0239	Lead Track Code 91	925
	0239	Purane Plastic Inc. Spots #20%-21	I Company
NDUS.	0239	Wesco Millwork Inc. Spot 23	6()
STRIL JRBA	0239	G.I. Industries Inc. Spots 27-28	9; 1
INDUSTRIAL— OBURBANK	0240 SPIKE SWIT(	ED Spot 03	15 1
ZONES	IS (024)	OUT 1 Continental Envelope Corp. of Calif.	•
NES		Spot 02	177
m m	024	3 Capital Tire Whse. Spots 03-#04#	17
l .			(P.10)
		•	- 1

(P.13)



Inc. 0101 **←** то ZONE I ZONE 10 PART L PART 2. " A" YD. "B" YD. MAIN LINE MAIN LINE FWY. FERNANDO SAN RD. GLENDALE INDUSTRIAL- GLENDALE-BURBANK ZONES ZONE I PART I. 9